PRINTED: 01/03/2012 FORM APPROVED

(X6) DATE

## Division of Health Care Facilities

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - MAIN BUILDING A. BUILDING B. WING TNL1936 10/10/2011 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **4200 MURFREESBORO PIKE** LIFE CARE CENTER OF HICKORY WOODS ANTIOCH, TN 37013 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID ID (X5) (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE **PREFIX PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) N 000 **Initial Comments** N 000 Based on the initial survey conducted on 10/10/11, it was determined the facility was in compliance with the Life Safety Code requirements of the Tennessee Department of Health, Board of Licensing Health Care Facilities and Chapter 1200-08-06 Standards for Nursing and its referenced publications. Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899 XO8H21 If continuation sheet 1 of 1

TITLE